

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

958
NNW
> 1
1.275 mi.
6730 ft.

**OVERFLW FROM OLD O/W SEPARATOR
3 AVENUE WORKOUT LOCATION
BROOKLYN, NY**

**NY Spills S108058398
N/A**

**Relative:
Higher**

**Actual:
13 ft.**

SPILLS:

Name: OVERFLW FROM OLD O/W SEPARATOR
Address: 3 AVENUE WORKOUT LOCATION
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0604062 / 2007-03-19
Facility ID: 0604062
Facility Type: ER
DER Facility ID: 316988
Site ID: 366945
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2006-07-12
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2006-07-12
CID: 409
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-07-12
Spill Record Last Update: 2007-03-19
Spiller Name: ERT DESK MIKE DAUGHTERY
Spiller Company: CON EDISON
Spiller Address: 222 1ST STREET
Spiller Company: 999
Contact Name: ERT DESK MIKE DAUGHTERY
DEC Memo: "03/19/07 - See e-docs for Con Ed report detailing cleanup and closure. 201093. see eDocs. "
Remarks: "1/2 GAL THAT WENT INTO A SEWER. IT CAME FROM A SEPERATOR PIT. THIS WAS DUE TO THE WEATHER. 201093."

All Materials:

Site ID: 366945
Operable Unit ID: 1124871
Operable Unit: 01
Material ID: 2114379
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported